

Disclaimers

1. Use of Technical Information

The technical information published on this website is intended and made available only to users who have the necessary professional and technical skills, knowledge and qualifications, as well as the necessary equipment and tools.

Specific repair or maintenance operations must be performed with the appropriate specified equipment and tools, and replacement parts or components. Any repair or maintenance operation undertaken by any user of this website on the basis of, as a result of or in connection with the technical information published on this website is performed under the sole responsibility of such user, and Toyota Motor Europe NV/SA, any of its affiliated companies and/or any of its national distributors cannot be held liable for any bodily injury, damage to property, loss expenses or any other damage, or any infringement to any laws or regulations, as a result of any such repair or maintenance operation.

2. Warranty information contained within these documents

Any information which specifically relates to the terms and conditions of any specific warranty action undertaken by Toyota Motor Europe NV/SA, any of its affiliated companies and/or any of its national distributors, and which is included in any document published on this website, does not constitute technical information.

Such information relates to past warranty actions undertaken by Toyota Motor Europe NV/SA, any of its affiliated companies and/or any of its national distributors, and, as a consequence, neither Toyota Motor Europe NV/SA nor any of its affiliated companies or any of its national distributors are bound by such warranty actions, or any term and condition thereof.

Under no circumstances shall such information constitute any undertaking, commitment or promise by Toyota Motor Europe NV/SA, any of its affiliated companies and/or any of its national distributors to apply, extend or renew such warranty action.

3. Upgrade or repair entitlement

The fact that a piece of technical information which relates to a specific upgrade or repair work for any specific range of vehicles has been published on this website, and that the vehicle belonging or used by a user of this website falls within such range, does not, as such, mean that the user's vehicle effectively needs to be upgraded or repaired or that they would be entitled to such upgrade or repair, whether against payment or under any warranty action.



TOYOTA

Technical Service Bulletin

**Chassis -
Powertrain**

Subject:

Steering Intermediate shaft knocking noise

Models:

PRIUS

Model codes:

ZVW30

CP-0005T-0113

INTRODUCTION

This Technical Service Bulletin is to inform you of the production change and repair method for the subject concern. Applicable to vehicles produced before the production change effective VIN's.

DESCRIPTION OF PHENOMENON

Some customers may experience and report a knocking noise from the steering when driving on bumpy road.

PRODUCTION CHANGE

The steering intermediate shaft #2 has been changed.

PRODUCTION CHANGE INFORMATION

Model code	Plant	Production change effective VIN	Implementation date
ZVW30	TSUTSUMI LINE NO.2	JTDKN3DU0C1577800	July 2012
	TSUTSUMI LINE NO.1	JTDKN3DU4C0336179	
	TOYOTA AUTO BODY	JTDKN36U305493228	

PARTS INFORMATION

Previous part number	Current part number	Part name	Quantity
45260-47060	45260-12710	Shaft assy steering intermediate #2	1

REPAIR PROCEDURE

Replace the steering intermediate shaft #2 according to the repair manual.